
Joining 12-72mm carrier tape with FC1272B Joint Tape




Tel: 44 1862 871 555 Fax: 44 1862 871 666 Email: mauk@btconnect.com


FC1272F

www.mauksmt.com


Joining 12mm embossed carrier tape using Fuji FC1272B Joint Tape




6 Bend the Joint Tape along a bending line and stick it on backside of a carrier tape.




O Peel a white cover and a positioning guide of the Joint Tape




(8) Bend the Joint Tape along a bending line and stick it on feeding holes side



9 Peel a transparent tape from L side to R side of the Joint Tape.




*Be sure a black sticks completely to the carrier tape.



Sold Europe & USA by: www.mauksmt.com


/: Mid America (UK) Ltd Hill House, Rockfield, Tain, IV 20 1RF, Scotland, UK Tel: 44 1862 871 555 Fax: 44 1862 871 666 email: mauk@btconnect.com


Joining 16mm embossed carrier tape using Fuji FC1272B Joint Tape



(A row of feeding holes must be along a guide line.)

- 6 Stick a carrier tape B setting it on a positioning guide and setting its cut end on a carrier tape A O Peel a white cover and a positioning guide of the Joint Tape 8 Bend the Joint Tape along a bending line and stick it on feeding holes side 0000 9 Peel a transparent tape from L side to R side of the Joint Tape. R side 0 0 L side
 - All completed
 ※Be sure a black sticks completely to the carrier tape.







Sold in Europe & USA by:

Mid America (UK) Ltd tel: 44 1862 871 555 fax: 44 1862 871 666 email: mauk@btconnect.com Hill House, Rockfield, Tain, IV 20 1RF, Scotland, UK


www.mauksmt.com

FC1272B PROCEDURE (For 24mm emboss carrier tape)







③ Peel a white cover of the Joint Tape up to a positioning guide.




- Stick a joint tape on the cover tape
 - ⑦ Peel a white cover and a positioning guide of the Joint Tape




⑧ Bend the Joint Tape along a bending line and stick it on feeding holes side



 ④ Set a carrier tape A on a positioning guide, and stick the cover tape downward on center of the Joint Tape (A row of feeding holes must be along a guide line.)





(5) Stick a carrier tape B setting it on a positioning guide and setting its cut end on the carrier tape A



Mid America (UK) Ltd Hill House, Rockfield, Tain, IV20 1RF, Scotland, UK

tel: 44 1862 871 555 fax: 44 1862 871 666 email: mauk@btconnect.com www.mauksmt.com 9 Peel a transparent tape from L side to R side of the Joint Tape.





FUJI CHEMICAL INDUSTRIAL CO., LTD.